

# Bulletin 33

All 6-year service visits until further



June 2022

As many manufacturers of electronic and mechanical products DASPOS have experienced lack of delivery from sub-suppliers with no information of when normal situations will arrive.



DASPOS is also hit by the fact!

We have found a replacement which performs satisfactorily and can do the job. The replacement fans only need some modification in the electronic inside the detectors and as such without any interference to the users.

We have kept a small stock for emergency issues, and hope that they will last until we again can get supplies.

We are very sorry for the development which unfortunately has hit a large part of all industries.

Please do not hesitate to contact [service@daspos.com](mailto:service@daspos.com) if you have questions or need assistance in any matters.

Thanks

A handwritten signature in black ink, appearing to be "T. Jorgensen". The signature is written in a cursive style with a long horizontal stroke extending to the right.

Torben Jorgensen CTO  
DASPOS A/S